

CITTY OF POMONA • PUBLIC WORKS DEPARTMENT ENVIRONMENTAL SERVICES DIVISION

	Site/File _		
Inspection	Work Ord	er (I)	

Storm Water Facility Inspection/Site Visit Report Form

☐ First Inspection	☐ Facility has closed or new Facility Information (see attache
	820 5. Re SERVOIR
	Activity: PLOSTIC RECYCL WaSIC:
Major Cross Street (s): RESERVOIR & LEXINGTON	
Is the facility covered under any other permits? (Check all that apply) ☐ Air Quality ☐ Hazmat business plan ☐ Und ☐ Fire Dept. (Storage) ☐ Hazardous waste generator ☐ Other	le ☐ Industrial Waste ☐ Aboveground storage tank ☐ r:
Is the facility covered under a storm water permit? □ Does not need coverage □ General (filed NOI) Does the facility have a SWPPP? □ Yes □ No	 □ No, but may need to (Refer to Regional Board) □ Individual NPDES
ACTIVITIES ASSESSMENT CI	HECKLIST
ACTIVITIES - Check each activity present at the site and evaluate its potential for pollutant discharge (PPD) : 1 = low potential, 2 = medium potential, 3 = high potential → Circled BMPs require your immediate attention - see back of this report.	APPLICABLE EFFECTIVENESS ACTIVITY RATING* Yes No PPD
A. MINIMUM BMPs - APPLICABLE TO ALL FACILITIES BMPs employed:	[1] [] [] 2 3 4 5
B. VEHICLE AND EQUIPMENT FUELING BMPs employed:	
C. VEHICLE AND EQUIPMENT WASHING/STEAM CLEANING BMPs employed:	
D. VEHICLE AND EQUIPMENT MAINTENANCE AND REPAIR BMPs employed:	
E. OUTDOOR LOADING/UNLOADING OF MATERIALS BMPs employed:	[X] [] [3] (1) (2) (8) (4) (5)
F. OUTDOOR PROCESS EQUIPMENT OPERATIONS AND MAINTENANCE BMPs employed:	[X] [] [3] (1) (2) (A) (4) (5)
G. OUTDOOR STORAGE OF RAW MATERIALS/PRODUCTS/CONTAINERS BMPs employed:	[×] [] [3] 1 2 3 4 5
H. WASTE HANDLING AND DISPOSAL BMPs employed:	[X] [] [2] (1) (2) (3) (%) (5)
I. CONTAMINATED OR ERODIBLE SURFACE AREAS BMPs employed:	
J. BUILDING AND GROUNDS MAINTENANCE BMPs employed:	
K. ROOFTOP EQUIPMENT BMPs employed:	
L. OUTDOOR DRAINAGE FROM INDOOR AREAS BMPs employed:	
M. OTHER (describe):	
* 1 No BMPs used and stormwater pollution likely 2 Some BMPs used but not expected a Source control BMPs used and very effective/structural BMPs need 5 All need	ffeetive 2 Company
This report is not a citation . It is furnished to the facility representative to assist in design runoff of pollutants to the storm drain system. A reinspection of your facility (\Box is requi	ing and evaluating Best Management Practices to prevent the red) (☐ is not required) to review correction of deficiencies e for a reinspection.
Print name of Facility Representative: Evaluation Aw.	Inspector: M. BROWA/

CITY OF POMONA PUBLIC WORKS DEPARTMENT ENVIRONMENTAL SERVICES DIVISION

Job Address 1820 S RESERVOIR

6

Correction Notice Noticia de Corrección Re-Inspections 620-2224

ite impections one and
G. arrown STONAGE OF MATERIAL
AWAITING TO BE BALED HAS
THE POTENTIAL TO BLOW AWAY OR
BE WASHED DWAY
PLEASE COVER & CONTRIN.
H. TRASH & DEBRIS PRESENT
THROUGHOUT FACILITY FROM
OPERATIONS. TRASH SHOULD BE
SUEPT UP PEGULARLY.
KETURN: 7/23/08
X Christ Van
WHEN THE ABOVE CORRECTIONS ARE MADE, PLEASE NOTIFY ENVIRONMENTAL SERVICES DIVISION FOR RE-INSPECTION. IF YOU HAVE ANY QUESTIONS, CALL 620-2224.
NOTE: OTHER CORRECTIONS MAY BE NEEDED PRIOR TO THE JOB FINAL.
INSPECTOR M. Brawn DATE 7/9/08

CITY OF POMONA PUBLIC WORKS DEPARTMENT ENVIRONMENTAL SERVICES DIVISION

Job Address 1820 S. RESERVAIR

Correction Notice Noticia de Corrección Re-Inspections 620-2224

Ne-inspections 020-2224
E. TRASH & DEBRIS FOUND IN
LOADING DOCK AREA.
PLEASE CLEAN UP LOADING DOLL
ROUTINELY.
F. OUTDOOR OPERATIONS CREATERIOT
OF TRASH & DEBRIS ON 5 SIDE
EXTEND FENCE TO TOUCH GROUND
+ INSTOLL SCHOOL NEST BOTTOM
OF FENCE TO CATEH DEBRIS,
INSTALL SCREEN OVER STORM
DRAINS TO CATEH DEBRIS
WHEN THE ABOVE CORRECTIONS ARE MADE, PLEASE NOTIFY ENVIRONMENTAL SERVICES DIVISION FOR RE-INSPECTION. IF YOU HAVE ANY QUESTIONS, CALL 620-2224.
NOTE: OTHER CORRECTIONS MAY BE NEEDED PRIOR TO THE JOB FINAL.
INSPECTOR M. BROWN DATE 7/9/08

Stormwater Inspection 1820 S Reservoir St Pomona, California



PHOTOGRAPH 1.

View of the fence along the W side of the facility.

The tenant was instructed to increase the fence length to touch the ground and place screen at the bottom to catch wind-blown debris. Tenant was also instructed to clean out gutter and place screen over gutter to prevent debris entering storm drain.

PHOTOGRAPH 2.


View of outdoor storage area on S side of facility.

The tenant was instructed to cover the storage piles and to increase sweeping frequency.

PHOTOGRAPH 3.

View of outdoor storage area on S side of facility.

The tenant was instructed to cover the storage piles and to increase sweeping frequency.





CITTY OF POMONA • PUBLIC WORKS DEPARTMENT ENVIRONMENTAL SERVICES DIVISION Storm Water Facility Inspection/Site Visit Report Form

	Site/File	
spection	Work Order (I)	

☐ First Inspection ☐ Response to Complaint	Excility has also J. T. T. T.
- The constitution	☐ Facility has closed or new Facility Information (see attac 1820 S. Reservoir
Contact Name: Emuno Lam Phone: Business Type	
Major Cross Street (s): RESERVOIR & LEXINGTON	
	one
s the facility covered under a storm water permit? Does not need coverage General (filed NOI) Does the facility have a SWPPP? Yes No	□ No, but may need to (Refer to Regional Board)□ Individual NPDES
ACTIVITIES ASSESSMENT	
ACTIVITIES - Check each activity present at the site and evaluate its potential for pollutant discharge (PPD) : 1 = low potential, 2 = medium potential, 3 = high potential → Circled BMPs require your immediate attention - see back of this report.	ACTIVITY RATING*
A. MINIMUM BMPs - APPLICABLE TO ALL FACILITIES BMPs employed:	[1] [] (1) (2) (3) (4) (5)
BMPs employed:	
VEHICLE AND EQUIPMENT WASHING/STEAM CLEANING BMPs employed:	
D. VEHICLE AND EQUIPMENT MAINTENANCE AND REPAIR BMPs employed:	[][][](1)(2)(3)(4)(5)
OUTDOOR LOADING/UNLOADING OF MATERIALS BMPs employed:	
OUTDOOR PROCESS EQUIPMENT OPERATIONS AND MAINTENANCE BMPs employed:	
OUTDOOR STORAGE OF RAW MATERIALS/PRODUCTS/CONTAINERS BMPs employed:	
. WASTE HANDLING AND DISPOSAL BMPs employed:	[][][](2)(3)(4)(5)
CONTAMINATED OR ERODIBLE SURFACE AREAS BMPs employed:	
BUILDING AND GROUNDS MAINTENANCE BMPs employed:	
ROOFTOP EQUIPMENT BMPs employed:	
OUTDOOR DRAINAGE FROM INDOOR AREAS BMPs employed:	[][][](2)(3)(4)(5)
OTHER (describe):	
No BMPs used and stormwater pollution likely ② Some BMPs used but not Source control BMPs used and very effective/structural BMPs need ③ All n	St. C. O. C. Dien
s report is not a citation . It is furnished to the facility representative to assist in design off of pollutants to the storm drain system. A reinspection of your facility (\square is required above. Please call (909) 620-2224 by	ning and evaluating Best Management Practices to prevent the
ility Representative Signature:	Date:
at name of Facility Representative: TONA CHEN	Date:

IMPORT & EXPORT INC.

Plastic Recycling Solution

Edmund Lam

1820 S. Reservoir Street, Pomona, CA 91766 Tel: (909) 868-0882 Fax: (909) 868-0330 Cell: (626) 688-7126 Email: macoedmund@yahoo.com